

Estimate



Customer:

Jordan Taylor
120 sq. ft. accessible brick wall area
St. Louis, Missouri

Cedar & Beam Builders
Illustrative project services
St. Louis, Missouri

Issued: 24 Sep 2026

Due: 24 Oct 2026

Scope: Repoint visibly deteriorated mortar joints within 120 square feet of accessible brick wall after a condition review. Include protection, joint preparation, compatible mortar allowance, placement, cleaning and cleanup. No structural rebuilding, water-intrusion diagnosis or high access.

Definition	Amount
Joint preparation labor (sq. ft.) 120.00 x \$9.00	\$1080.00
Area protection (job) 1.00 x \$140.00	\$140.00
Masonry condition and access review (job) 1.00 x \$225.00	\$225.00
Final cleaning and cleanup (job) 1.00 x \$210.00	\$210.00
Repointing labor (sq. ft.) 120.00 x \$13.00	\$1560.00
Mortar material allowance (job) 1.00 x \$270.00	\$270.00
	SubTotal \$3485.00
	Tax 0% \$0.00
	Total \$3485.00

Notes:

Illustrative example only; prices are not market rates. Tax and markup not included. No structural rebuilding, brick replacement, waterproofing design, high scaffolding or concealed damage correction.

customer signature