

Estimate



Customer:

Jordan Taylor
111 sq m residential driveway
Sheffield

Cedar & Beam Builders
Illustrative project services
Sheffield

Issued: 25 Sep 2026

Due: 25 Oct 2026

Scope: Clean and seal 111 sq m of accessible tarmac driveway after a condition review. No resurfacing or pothole repair.

Definition	Amount
Surface review and setup (lump sum) 1.00 x £124.00	£124.00
Driveway cleaning and preparation (sq m) 111.00 x £2.41	£267.51
Limited crack filling (metre) 24.40 x £9.20	£224.48
Sealer material allowance (lump sum) 1.00 x £448.00	£448.00
Sealer application labour (sq m) 111.00 x £3.62	£401.82
Protection removal and clean-up (lump sum) 1.00 x £100.00	£100.00
SubTotal	£1565.81
Tax 0%	£0.00
Total	£1565.81

Notes:

Fictional UK example. Rates are illustrative, not market prices. 0% tax and no markup are example inputs. Check rates, tax and unlisted work for your job.

customer signature