

Estimate



Customer:

Jordan Taylor
Three localised driveway patches
York

Cedar & Beam Builders
Illustrative project services
York

Issued: 25 Sep 2026

Due: 25 Oct 2026

Scope: Repair three nonstructural surface defects totaling 2.8 sq m on an accessible concrete driveway after site review.

Definition	Amount
Work-area protection (lump sum) 1.00 x £84.00	£84.00
Limited concrete removal (sq m) 2.80 x £103.30	£289.24
Condition review and layout (lump sum) 1.00 x £144.00	£144.00
Joint touch-up allowance (metre) 5.50 x £23.60	£129.80
Waste and clean-up (lump sum) 1.00 x £140.00	£140.00
Repair material allowance (lump sum) 1.00 x £256.00	£256.00
Patch placement and finish labour (sq m) 2.80 x £206.70	£578.76
SubTotal	£1621.80
Tax 0%	£0.00
Total	£1621.80

Notes:

Fictional UK example. Rates are illustrative, not market prices. 0% tax and no markup are example inputs. Check rates, tax and unlisted work for your job.

customer signature