

Estimate



Customer:
Jordan Taylor
Four-head zone repair
Mesa, Arizona

Cedar & Beam Builders
Illustrative project services
Mesa, Arizona

Issued: 24 Sep 2026
Due: 24 Oct 2026
Scope: Repair four identified sprinkler heads in one accessible existing zone. Include system review, selected head allowance, replacement labor, two small fitting allowances, zone operation check and cleanup. Controller replacement, new trenching and buried-pipe diagnosis excluded.

Definition	Amount	
Zone review and fault marking (job) 1.00 x \$155.00	\$155.00	
Sprinkler head allowance (each) 4.00 x \$38.00	\$152.00	
Head replacement labor (each) 4.00 x \$78.00	\$312.00	
Small fitting allowance (each) 2.00 x \$28.00	\$56.00	
Zone operation check (job) 1.00 x \$115.00	\$115.00	
Cleanup and surface reset (job) 1.00 x \$95.00	\$95.00	
	SubTotal	\$885.00
	Tax 0%	\$0.00
	Total	\$885.00

Notes:
Illustrative example only; prices are not market rates. Tax and markup not included. No controller replacement, valve repair, buried main repair, new trenching or full-system redesign.

customer signature