

Estimate



Customer:
Jordan Taylor
One existing chimney junction
Halifax, NS

Cedar & Beam Builders
Fictional Canadian project services
Halifax, NS

Issued: 25 Sep 2026

Due: 25 Oct 2026

Scope: Replace failed flashing at one chimney-to-roof junction while retaining otherwise sound roof covering and masonry.

Definition	Amount
Roof covering reinstatement (job) 1.00 x C\$410.00	C\$410.00
Water-shedding check and cleanup (job) 1.00 x C\$250.00	C\$250.00
Flashing material allowance (linear ft.) 32.00 x C\$56.00	C\$1792.00
Form and install flashing (linear ft.) 28.00 x C\$73.00	C\$2044.00
Lift adjoining covering (job) 1.00 x C\$370.00	C\$370.00
Old flashing removal (linear ft.) 28.00 x C\$24.00	C\$672.00
Roof access and protection (job) 1.00 x C\$505.00	C\$505.00
SubTotal	C\$6043.00
Tax 0%	C\$0.00
Total	C\$6043.00

Notes:
Fictional CAD prices; 0% tax, no markup. Confirm GST/HST/PST. No chimney rebuild, roof replacement or interior water-damage repair.

customer signature