

Estimate



Customer:

Jordan Taylor
One existing shower enclosure
Tampa, Florida

Cedar & Beam Builders
Illustrative project services
Tampa, Florida

Issued: 25 Sep 2026

Due: 25 Oct 2026

Scope: Remove failed grout and sealant from sound shower wall tile joints, regROUT and reseal accessible junctions.

Definition	Amount	
Joint clean and dry (job) 1.00 x \$135.00	\$135.00	
Grout removal (sq. ft.) 88.00 x \$7.00	\$616.00	
Condition check and masking (job) 1.00 x \$145.00	\$145.00	
Final clean and handoff (job) 1.00 x \$90.00	\$90.00	
Sealant renewal (linear ft.) 32.00 x \$6.00	\$192.00	
Regrouting labor (sq. ft.) 88.00 x \$8.00	\$704.00	
Grout allowance (job) 1.00 x \$105.00	\$105.00	
	SubTotal	\$1987.00
	Tax 0%	\$0.00
	Total	\$1987.00

Notes:

Illustrative example; not market rates. Tax and markup not included. No tile replacement, concealed leak repair or waterproofing guarantee.

customer signature